



October 6, 2009

Dear Customer:

As a follow up to our PTN (MQ2090302) letter dated May 4th, 2009, we would like to update you on the status of our Mountain Top factory closure.

After careful consideration of a number of factors, we have decided to extend the operation of our Mountain Top factory by up to 6 months.

This decision was influenced by the following:

1. Our commitment to you to build all your required last time buy quantities to bridge the transition period may require that we have additional capacity available, especially in light of current demand.
2. Market conditions have improved since the decision was first taken to close the factory. Even with the closure of Mountain Top, we are confident that we have the capacity to handle our long term demand; however, the transitional demand on all of our factories makes it prudent to leave the factory open longer to insure that we can meet all of our customer's immediate needs.

As a result of this decision, we have also decided to revisit our qualification schedules for some of the replacement products. Our earlier schedules were based on previous qualification work that was done at the receiving factories. Given the additional time that the extension in the Mountain Top closure has created, we see an opportunity to further align a few of the processes so that they more closely mirror the manufacturing processes that are used in Mountain Top. We see this as an opportunity to lower the transfer risk. We are planning on revising the qualification time lines for some of the products, with fully qualified samples available in May 2010, and engineering samples available two months earlier.

As we stated to you in our earlier letter, while we had set an aggressive date for the closure of the factory, we would remain flexible and adjust our dates as the situation required. We must stress however, that while we have extended the operation of the factory, we do not foresee any additional extensions and therefore still must adhere to a very rigorous schedule with our customers in order to insure a smooth closure of our factory, as outlined previously. Given one of the drivers of our closure delay is the need to build bridge inventory, it is important that you provide your initial last time buy quantities by November 2009. We do not expect your final last time buy adjustments until 2 months after we deliver qualified samples.

Please continue to work with the Fairchild sales force on the details surrounding our factory closure.

With Best Regards

Fairchild Semiconductor  
Transfer Team

<b>Discontinued Product(s)</b>	<b>Manufacturer of Replacement Product(s)</b>	<b>Direct Replacement Product(s) - same spec</b>	<b>Early Sample Availability</b>	<b>Expected Final Automotive Qualification</b>
F59314548C	Fairchild/BK	F59314548D	March-10	May-10
FDB045AN08A0_F085	Fairchild/BK	FDB045AN08A0_F085A	March-10	May-10
FDB060AN08A0_NB82085	Fairchild/BK	FDB060AN08A0_SN00089	March-10	May-10
FDB14AN06LA0_SB82272	Fairchild/BK	FDB14AN06LA0_SN00115	March-10	May-10
FDB20AN06A0_B82014A	Fairchild/BK	FDB20AN06A0_SN00086	March-10	May-10
FDB2532_SB82023A	Fairchild/BK	FDB2532_SN00096	March-10	May-10
FDB2552_SB82178	Fairchild/BK	FDB2552_SN00095	March-10	May-10
FDB3632_SB82115	Fairchild/BK	FDB3632_SN00112	March-10	May-10
FDB3652_F085	Fairchild/BK	FDB3652_F085A	March-10	May-10
FDB3672_F085	Fairchild/BK	FDB3672_F085A	March-10	May-10
FDB3672_SB82072	Fairchild/BK	FDB3672_SN00091	March-10	May-10
FDB42AN15A0_SB82021A	Fairchild/BK	FDB42AN15A0_SN00093	March-10	May-10
FDB8441_F085	Fairchild/BK	FDB8441_F085A	March-10	May-10
FDB8441_F085	Fairchild/SL	FDB8441_F085A	March-10	May-10
FDB8442_F085	Fairchild/SL	FDB8442_F085A	March-10	May-10
FDB8443_F085	Fairchild/SL	FDB8443_F085A	March-10	May-10
FDB8444TS	Fairchild/SL	FDB8444TS_F085A	March-10	May-10
FDB8832_F085	Fairchild/SL	FDB8832_F085A	March-10	May-10
FDB8860_SB82193	Fairchild/SL	FDB8860_SN00039	March-10	May-10
FDB8860_SB82194	Fairchild/SL	FDB8860_SN00040	March-10	May-10
FDB8870_F085	Fairchild/SL	FDB8870_F085A	March-10	May-10
FDB8896_F085	Fairchild/SL	FDB8896_F085A	March-10	May-10
FDBS09H04	Fairchild/BK	FDBS09H04_F085A	March-10	May-10
FDC5661N_F085	Fairchild/SL	FDC5661N_F085A	March-10	May-10
FDD120AN15A0_W82016B	Fairchild/BK	FDD120AN15A0_SN00092	March-10	May-10
FDD13AN06A0_F085	Fairchild/BK	FDD13AN06A0_F085A	March-10	May-10
FDD14AN06LA0_SB82165	Fairchild/BK	FDD14AN06LA0_SN00101	March-10	May-10
FDD14AN06LA0_SB82248	Fairchild/BK	FDD14AN06LA0_SN00102	March-10	May-10
FDD16AN08A0_F085	Fairchild/BK	FDD16AN08A0_F085A	March-10	May-10
FDD16AN08A0_SB82033A	Fairchild/BK	FDD16AN08A0_SN00088	March-10	May-10
FDD20AN06A0_F085	Fairchild/BK	FDD20AN06A0_F085A	March-10	May-10
FDD20AN06A0_SB82269	Fairchild/BK	FDD20AN06A0_SN00087	March-10	May-10
FDD24AN06LA0_F085	Fairchild/BK	FDD24AN06LA0_F085A	March-10	May-10
FDD24AN06LA0_SB82179	Fairchild/BK	FDD24AN06LA0_SN00098	March-10	May-10
FDD24AN06LA0_SB82249	Fairchild/BK	FDD24AN06LA0_SN00099	March-10	May-10
FDD2572_F085	Fairchild/BK	FDD2572_F085A	March-10	May-10
FDD2572_SB82094	Fairchild/BK	FDD2572_SN00113	March-10	May-10
FDD26AN06A0_F085	Fairchild/BK	FDD26AN06A0_F085A	March-10	May-10
FDD26AN06A0_SB82186	Fairchild/BK	FDD26AN06A0_SN00085	March-10	May-10
FDD3682_F085	Fairchild/BK	FDD3682_F085A	March-10	May-10
FDD3682_NB82112	Fairchild/BK	FDD3682_SN00110	March-10	May-10
FDD5810_F085	Fairchild/BK	FDD5810_F085A	March-10	May-10
FDD5810_SB82124	Fairchild/BK	FDD5810_SN00097	March-10	May-10
FDD8424H_F085	Fairchild/SL	FDD8424H_F085A	March-10	May-10
FDD8444L_F085	Fairchild/SL	FDD8444L_F085A	March-10	May-10
FDD8870_F085	Fairchild/SL	FDD8870_F085A	March-10	May-10

FDD8896_F085	Fairchild/SL	FDD8896_F085A	March-10	May-10
FDI8441_F085	Fairchild/SL	FDI8441_F085A	March-10	May-10
FDI8442_F085	Fairchild/SL	FDI8442_F085A	March-10	May-10
FDMS2380_F085	Fairchild/BK	FDMS2380_F085A	March-10	May-10
FDMS2380_SB82099	Fairchild/BK	FDMS2380_SN00100	March-10	May-10
FDP13AN06A0_SW82126	Fairchild/BK	FDP13AN06A0_SN00109	March-10	May-10
FDP2710_F085	Fairchild/BK	FDP2710_F085A	March-10	May-10
FDP3682_SB82034	Fairchild/BK	FDP3682_SN00090	March-10	May-10
FDP42AN15A0_SB82024A	Fairchild/BK	FDP42AN15A0_SN00094	March-10	May-10
FDP8441_F085	Fairchild/SL	FDP8441_F085A	March-10	May-10
FDP8442_F085	Fairchild/SL	FDP8442_F085A	March-10	May-10
FDP8443_F085	Fairchild/SL	FDP8443_F085A	March-10	May-10
FDP8870_F085	Fairchild/SL	FDP8870_F085A	March-10	May-10
FDP8896_F085	Fairchild/SL	FDP8896_F085A	March-10	May-10
FDPS09H04	Fairchild/BK	FDPS09H04_F085A	March-10	May-10
FDSS2407	Fairchild/BK	FDSS2407_F085A	March-10	May-10
FDSS2407_SB82086	Fairchild/BK	FDSS2407_SN00062	March-10	May-10
FDSS2407_SB82097	Fairchild/BK	FDSS2407_SN00063	March-10	May-10
FGB3040CS	Fairchild/BK	FGB3040CS_F085A	March-10	May-10
FGB3040CS_SB82142	Fairchild/BK	FGB3040CS_SN00057	March-10	May-10
FGB3236_F085	Fairchild/BK	FGB3236_F085A	March-10	May-10
FGB3236_SN00003	Fairchild/BK	FGB3236_SN00058	March-10	May-10
FGI3236_F085	Fairchild/BK	FGI3236_F085A	March-10	May-10
FGI3236_SN00004	Fairchild/BK	FGI3236_SN00059	March-10	May-10
FTCS120PS4PA	Fairchild/SL	FTCS120PS4PC	March-10	May-10
HUF75307D3ST_SB78016	Fairchild/BK	HUF75307D3ST_SN00079	March-10	May-10
HUF75329D3ST_R4820	Fairchild/BK	HUF75329D3ST_SN00080	March-10	May-10
HUF75345P3_R4908	Fairchild/BK	HUF75345P3_SN00082	March-10	May-10
HUF75639S3ST_S2515	Fairchild/BK	HUF75639S3ST_SN00083	March-10	May-10
HUF76409D3ST_S2457	Fairchild/BK	HUF76409D3ST_SN00065	March-10	May-10
HUF76409D3ST_SB82270	Fairchild/BK	HUF76409D3ST_SN00066	March-10	May-10
HUF76419S3ST_R4908	Fairchild/BK	HUF76419S3ST_SN00071	March-10	May-10
HUF76629D3ST_SB82250	Fairchild/BK	HUF76629D3ST_SN00072	March-10	May-10
HUF76633P3_R4883	Fairchild/BK	HUF76633P3_SN00075	March-10	May-10
HUF76633S3ST_SB82274	Fairchild/BK	HUF76633S3ST_SN00073	March-10	May-10
HUF76639S3ST_SB82190	Fairchild/BK	HUF76639S3ST_SN00076	March-10	May-10
HUF76639S3ST_SB82251	Fairchild/BK	HUF76639S3ST_SN00077	March-10	May-10
HUF76645S3ST_R4881	Fairchild/BK	HUF76645S3ST_SN00078	March-10	May-10
HUFA75307T3ST	Fairchild/BK	HUFA75321D3ST_F085A	March-10	May-10
HUFA75344P3_SB82066	Fairchild/BK	HUFA75344P3_SN00107	March-10	May-10
HUFA75344S3	Fairchild/BK	HUFA75344S3_F085A	March-10	May-10
HUFA75344S3ST_R4966	Fairchild/BK	HUFA75344S3ST_SN00081	March-10	May-10
HUFA75639S3ST	Fairchild/BK	HUFA75639S3ST_F085A	March-10	May-10
HUFA75639S3ST_S2457	Fairchild/BK	HUFA75639S3ST_SN00084	March-10	May-10
HUFA75842P3_SB82121	Fairchild/BK	HUFA75842P3_SN00060	March-10	May-10
HUFA75852G3_SB82025A	Fairchild/BK	HUFA75852G3_SN00061	March-10	May-10
HUFA76407DK8T	Fairchild/BK	HUFA76407DK8T_F085A	March-10	May-10
HUFA76407P3_SB82130	Fairchild/BK	HUFA76407P3_SN00064	March-10	May-10
HUFA76409D3ST	Fairchild/BK	HUFA76409D3ST_F085A	March-10	May-10
HUFA76409D3ST_B76008A	Fairchild/BK	HUFA76409D3ST_SN00067	March-10	May-10
HUFA76409D3ST_R4974	Fairchild/BK	HUFA76409D3ST_SN00068	March-10	May-10
HUFA76413DK8T	Fairchild/BK	HUFA76413DK8T_F085A	March-10	May-10

HUFA76413DK8T_B76001A	Fairchild/BK	HUFA76413DK8T_SN00069	March-10	May-10
HUFA76419D3ST	Fairchild/BK	HUFA76419D3ST_F085A	March-10	May-10
HUFA76419D3ST_SB82041A	Fairchild/BK	HUFA76419D3ST_SN00070	March-10	May-10
HUFA76429D3ST_F085	Fairchild/BK	HUFA76429D3ST_F085A	March-10	May-10
HUFA76633S3ST_S2575	Fairchild/BK	HUFA76633S3ST_SN00074	March-10	May-10
HUFA76645S3ST_F085	Fairchild/BK	HUFA76645S3ST_F085A	March-10	May-10
ISL9V2040D3ST	Fairchild/BK	ISL9V2040D3ST_F085A	March-10	May-10
ISL9V2040S3ST	Fairchild/BK	ISL9V2040S3ST_F085A	March-10	May-10
ISL9V2040S3ST_B9V002B	Fairchild/BK	ISL9V2040S3ST_SN00056	March-10	May-10
ISL9V2540S3ST	Fairchild/BK	ISL9V2540S3ST_F085A	March-10	May-10
ISL9V2540S3ST_SB49015	Fairchild/BK	ISL9V2540S3ST_SN00105	March-10	May-10
ISL9V3036D3ST_R4970	Fairchild/BK	ISL9V3036D3ST_SN00049	March-10	May-10
ISL9V3036S3ST	Fairchild/BK	ISL9V3036S3ST_F085A	March-10	May-10
ISL9V3036S3ST_SB82029A	Fairchild/BK	ISL9V3036S3ST_SN00050	March-10	May-10
ISL9V3040D3ST	Fairchild/BK	ISL9V3040D3ST_F085A	March-10	May-10
ISL9V3040D3ST_B49006A	Fairchild/BK	ISL9V3040D3ST_SN00041	March-10	May-10
ISL9V3040D3ST_R4940	Fairchild/BK	ISL9V3040D3ST_SN00042	March-10	May-10
ISL9V3040D3ST_R4956	Fairchild/BK	ISL9V3040D3ST_SN00043	March-10	May-10
ISL9V3040D3ST_R4969	Fairchild/BK	ISL9V3040D3ST_SN00044	March-10	May-10
ISL9V3040D3ST_SB82253	Fairchild/BK	ISL9V3040D3ST_SN00045	March-10	May-10
ISL9V3040P3	Fairchild/BK	ISL9V3040P3_F085A	March-10	May-10
ISL9V3040S3ST	Fairchild/BK	ISL9V3040S3ST_F085A	March-10	May-10
ISL9V3040S3ST_R4969	Fairchild/BK	ISL9V3040S3ST_SN00046	March-10	May-10
ISL9V3040S3ST_R4975	Fairchild/BK	ISL9V3040S3ST_SN00047	March-10	May-10
ISL9V3040S3ST_SB82252	Fairchild/BK	ISL9V3040S3ST_SN00048	March-10	May-10
ISL9V5036P3_F085	Fairchild/BK	ISL9V5036P3_F08A5	March-10	May-10
ISL9V5036S3	Fairchild/BK	ISL9V5036S3_F085A	March-10	May-10
ISL9V5036S3_SB82027C	Fairchild/BK	ISL9V5036S3_SN00103	March-10	May-10
ISL9V5036S3ST	Fairchild/BK	ISL9V5036S3ST_F085A	March-10	May-10
ISL9V5036S3ST_NB82031B	Fairchild/BK	ISL9V5036S3ST_SN00051	March-10	May-10
ISL9V5036S3ST_R4971	Fairchild/BK	ISL9V5036S3ST_SN00052	March-10	May-10
ISL9V5036S3ST_SB82026C	Fairchild/BK	ISL9V5036S3ST_SN00104	March-10	May-10
ISL9V5036S3ST_SB82065	Fairchild/BK	ISL9V5036S3ST_SN00053	March-10	May-10
ISL9V5036S3ST_SB82170	Fairchild/BK	ISL9V5036S3ST_SN00054	March-10	May-10
ISL9V5045S3ST	Fairchild/BK	ISL9V5045S3ST_F085A	March-10	May-10
PCF33468	Fairchild/SL	PCFA33468F6	March-10	May-10
PCF33474	Fairchild/SL	PCFA33474F6	March-10	May-10
PCF75337W_S2496	Fairchild/BK	PCF75337W_SN00106	March-10	May-10
PCFA82544D_SB82133	Fairchild/BK	PCFA82544D_SN00108	March-10	May-10
PCFA82755D_SB82132	Fairchild/BK	PCFA82755D_SN00111	March-10	May-10
PCFA83535D_SB82134	Fairchild/BK	PCFA83535D_SN00114	March-10	May-10
PCGA3056W	Fairchild/BK	PCGA49451W6	March-10	May-10
PCGA49452W	Fairchild/BK	PCGA49452W6	March-10	May-10
PCGA49455W	Fairchild/BK	PCGA49455W6	March-10	May-10
PCGA49456D	Fairchild/BK	PCGA49456D6	March-10	May-10
<b>Discontinued Product(s)</b>	<b>Manufacturer of Replacement Product(s)</b>	<b>Indirect Replacement Product(s) - new spec</b>		
FDB045AN08A0_SB82174	Fairchild	FDB045AN08A0_F085A	N/A	N/A
FDB5800_F085	Fairchild	None	N/A	N/A
FDD8444L	Fairchild	FDD8444L_F085A	N/A	N/A

FDD8447L_F085	Fairchild	None	N/A	N/A
FDN5632N_F085	Fairchild	None	N/A	N/A
FGD2N40L	Fairchild	FGD3N60LSDTM_F085A	N/A	N/A
HGT1S14N36G3VLT	Fairchild	ISL9V3036S3ST_F085A	N/A	N/A
HGT1S14N36G3VLT_SB82183	Fairchild	ISL9V3036S3ST_F085A	N/A	N/A
HGT1S14N37G3VLS_R4662	Fairchild	ISL9V3036S3ST_F085A	N/A	N/A
HGT1S14N41G3VLS_R4875	Fairchild	ISL9V3040S3ST_F085A	N/A	N/A
HGT1S20N36G3VLS_R4737	Fairchild	ISL9V5036S3ST_F085A	N/A	N/A
HUF75321S3ST_R4908	Fairchild	FDB20AN06A0	N/A	N/A
HUF75339S3ST_R4935	Fairchild	FDB13AN06A0	N/A	N/A
HUF75345P3_R4743	Fairchild	FDP5500_F085	N/A	N/A
HUF76437S3ST_SB82271	Fairchild	None	N/A	N/A
HUFA75344P3_F085	Fairchild	FDP5500_F085	N/A	N/A
HUFA75345P3	Fairchild	FDP5500_F085	N/A	N/A
HUFA75645P3	Fairchild	FDP3652	N/A	N/A
HUFA76404DK8T_SB82040A	Fairchild	HUFA76407DK8T_F085A	N/A	N/A
HUFA76404DK8T_SB82047	Fairchild	HUFA76407DK8T_F085A	N/A	N/A
HUFA76407D3ST	Fairchild	None	N/A	N/A
HUFA76409D3ST_NR4974	Fairchild	HUFA76409D3ST_SN00068	N/A	N/A
HUFA76409T3ST_B76004A	Fairchild	None	N/A	N/A
HUFA76609D3ST_F085	Fairchild	None	N/A	N/A
HUFA76609D3ST_SB82093	Fairchild	None	N/A	N/A
ISL9V3040S3ST_R4956	Fairchild	ISL9V3040S3ST_F085A	N/A	N/A
ISL9V5036S3_NB82032A	Fairchild	FGI3236_SN00059	N/A	N/A
ISL9V5036S3ST_SB82184	Fairchild	None	N/A	N/A
ISL9V5036S3ST_SB82191	Fairchild	None	N/A	N/A
RFD14N05LSM9A_S2515	Fairchild	None	N/A	N/A
RFD3055LESM9A_R4383	Fairchild	None	N/A	N/A